



FIGURE II-33. Tank 15 Annulus by Wide-Angle Camera, 1976. This downward view shows salt deposits from two leak sites low on the primary wall.